

Under Review Notification

Raised By: Scott Cameron

Product #: RBD412-729-011

Date: Nov 3 2017

Product Name: GROUND HANDLING WHEELS

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review ("Bluefiles")		
RBD412-729-011	RBD412-729-011 Rev 2	Y	N	N	Y	N	N	N	17-737	Build to updated drawing
RBD3333-1	RBD412-729-011 Rev 2	N	N	N	N	N	Y	N	17-737	Build to updated drawing
RBD3336-1	RBD412-729-011 Rev 2	Y	N	N	N	N	Y	N	17-737	Build to updated drawing
RBD3233-041	RBD3233-041 Rev 2	Y	N	N	Y	N	N	N	17-737	Build to updated drawing
RBD3233-041-7	RBD3233-041 Rev 2	N	N	N	N	N	N	N	17-737	Build to updated drawing

Description of Issue:

RBD412-729-011:

RBD3333-1 mounting hole locations need to change for 76508 substitution

RBD3337-25 wrong nut part number, does not fit inside, needs reduced OD nut

RBD3336-1 modified jack, original 76508 discontinued, alternate cannot be modified per print

RBD3233-041:

RBD3233-041-7 is too long, original D3233-041-7 was correct

Case 10073 / NCR17-6579

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider